

CHEVROLET SPARK - No Airbags



TECHNICAL SHEET





0.00 max. 17.00 - Adult Occupant





16.29 max. 49.00 - Child Occupant





CAR DETAILS

SAFETY EQUIPMENT

Tested model: Chevrolet Spark, LHD Year of publication: 2014 Made in: Corea del Sur

NO

NO

Crash test weight: Kg 1034 Test valid for: Mercado de Latin NCAP Body type: 4 door compact

| Front seatbelt pretensioners |
|-----------------------------------|
| Front seatbelt pretensioners pass |
| Driver frontal airbag |
| Front passenger frontal airbag |
| Cide heads aideans |

| Driver frontal airbag | NO |
|--------------------------------|----|
| Front passenger frontal airbag | NO |
| Side body airbags | NO |
| Side head airbags | NO |

| Driver knee airbag | NO |
|--------------------|----|
| SBR | NO |
| ABS | NO |
| ISOFIX anchorages | NO |

NO



ADULT OCCUPANT PROTECTION







PROTECTION GOOD **ADEQUATE** MARGINAL **WEAK** POOR

SIDE IMPACT TEST (UNECE 95) *

NOT performed

CABIN STRUCTURE

Passenger Airbag Switch

UNSTABLE



COMMENTS

Adult occupant: The protection offered to the driver and passenger head was poor and for this reason the star capping was applied. Driver's chest protection was poor due to contact with the steering wheel. The passengers' knees could impact with dangerous structures in the dashboard lie the Tran fascia tube. The bodyshell was rated as unstable. The bodyshell was not capable of withstanding any further loading.

Dynamic score: 9.95 (max 16) CRS Instalation Score: 4.34 (max 12) Vehicle assessment score: 2 (max 21)

CHILD RESTRAINT SYSTEM

| | CHILD RESTRAINT | DYNAMIC SCORE | CRS TYPE | ADJUST | POSITION |
|--------------------|--------------------------------|---------------|----------|--------|----------|
| 18 month old child | Peg Perego Primo Viaggio T.Fix | 7.95 (8 max) | 0+ | Belted | RWF |
| 3 year old child | Peg Perego Viaggio 0 +1 switch | 2 (8 max) | 1 | Belted | FWF |



COMMENTS

Child occupant: The child seat for the 3 year old child was unable to prevent excessive forward movement during the impact and offered low protection to neck and chest. The dynamic performance of the 18 months child restraint was adequate. Most of the CRS that were tested for installation failed. The short length of the rear seatbelts were a problem to properly install the CRS.

CRS INSTALLATION ASSESSMENT

| | | 2ND ROW | | | |
|----------------|---|---------|------|--------|-------|
| REFERENCE LIST | | RIGHT | LEFT | CENTER | RIGHT |
| Group 0+ | Peg Perego Viaggio Switchable | Fail | Fail | Fail | Fail |
| Group 0+ | Roemer Baby Safe | Fail | Fail | Fail | Fail |
| Group 0+ | Bébé Confort Streety Fix / Maxi Cosi Citi SPS | Fail | Pass | Fail | Pass |
| Group I | Peg Perego Viaggio Switchable FWF | Fail | Pass | Fail | Pass |
| Group I | Graco Cadeira Nautilus FWF | Fail | Pass | Fail | Pass |
| Group II/III | Graco Cadeira Nautilus | Fail | Pass | Fail | Pass |
| MANUFACTURER | | RIGHT | LEFT | CENTER | RIGHT |
| Q1.5 | Peg Perego Primo Viaggio Tri Fix | Fail | Pass | Fail | Pass |
| Q3 | Peg Perego Viaggio Switchable | Fail | Pass | Fail | Pass |

