

# TOYOTA HILUX / SW4 / FORTUNER + 3 Airbags



# **TECHNICAL SHEET**






15.71 max. 17.00 - Adult Occupant









# **CAR DETAILS**

Tested model: Toyota Hilux / SW4 / Fortuner Year of publication: 2015 Made in: Thailand & Argentina

Body type: Double cab Pick up / SUV Crash test weight: Kg 2309 Test valid for: Latin NCAP market

## **SAFETY EQUIPMENT**


Front seatbelt pretensioners	YES
Front seatbelt pretensioners pass	YES
Driver frontal airbag	YES
Front passenger frontal airbag	YES
Side body airbags	NO
Side head airbags	NO

Driver knee airbag	YES
SBR	YES
ABS	YES

ISOFIX anchorages YES



# **ADULT OCCUPANT PROTECTION**



SIDE IMPACT TEST (UNECE 95) \*

**PASS** 


#### **BODYSHELL INTEGRITY**

**STABLE** 



## **COMMENTS**

Adult occupant: - In the frontal impact the driver and passenger heads were well protected by the driver and passenger airbags. The driver and passenger chests received at least adequate protection. The driver knee airbag improved knee protection. Both seatbelts were equipped with pretensioners and load limiters. The passengers' knees areas did not show high risk structures. The bodyshell was rated as stable and was capable of withstanding further loading. The model could meet the requirements of the UN95 side impact test.



Dynamic score: 15.25 (max 16)

Installation score: 12.00 (max 12)

Vehicle assessment score:

17.00 (max 21)

#### **CHILD RESTRAINT SYSTEM**

	CHILD RESTRAINT	DYNAMIC SCORE	CRS TYPE	ADJUST	POSITION
18 month old child	TAKATA MIDI 2	7.25 (8 max)	0+	ISOFIX	RWF
3 year old child	TAKATA MIDI 2	8.00 (8 max)	1	ISOFIX	RWF



## **COMMENTS**

Child occupant: – The ISOFIX child seat for the 1  $\frac{1}{2}$  and 3 year old child dummies were able to prevent excessive forward movement during the impact and offered good protection for the dummies. The 1  $\frac{1}{2}$  and 3 year old Child dummies were positioned Rearward facing using i-Size approved CRS. The CRS installation achieved full points considering the exempted positions and presented a clear installation guide in the manual. The vehicle had warning labels explaining the hazards associated with installing a rearward facing child seat on the front passenger seat with an active airbag. Passenger airbag disconnection is possible and properly signalled. The car is marked as i-size.

#### **CRS INSTALLATION ASSESSMENT**

				2ND ROW	
REFERENCE LIST		RIGHT	LEFT	CENTER	RIGHT
Grupo 0+	Peg Perego Viaggio Switchable	Pass	Pass	Exempt	Pass
Grupo 0+	Roemer Baby Safe	Exempt	Pass	Exempt	Pass
Grupo 0+	Bébé Confort Streety Fix / Maxi Cosi Citi SPS	Pass	Pass	Exempt	Pass
Grupo I	Peg Perego Viaggio Switchable FWF	Pass	Pass	Exempt	Pass
Grupo I	Graco Cadeira Nautilus FWF	Pass	Pass	Exempt	Pass
Grupo II/III	Graco Cadeira Nautilus	Pass	Pass	Exempt	Pass
MANUFACTURER		RIGHT	LEFT	CENTER	RIGHT
Q1.5	Römer BabySafe + ISOFIX Base	Exempt	Pass	Exempt	Pass
Q3	Römer Duo Plus	Exempt	Pass	Exempt	Pass

